



# **TRMM Flight Operations Monthly Status Review (MSR)**

August 29th, 2001



# FOT Subsystem Overview

---

- Operations Status
  - Flight Ops Summary - Lou Kurzmilller
  - Electrical - Andy Calloway
  - Thermal - Dave Sepan
  - RCS & RF / Comm. - Dave Sepan
  - ACS & FDS / C&DH - Mark Fioravanti
  - Power & Deployables - Justin Knavel
  - LIS - Justin Knavel
  - CERES & VIRS - Mark Fioravanti
  - TMI - Dave Sepan
  - PR - Andy Calloway
  - Ground System - Andy Calloway
  - Upcoming Activities - Andy Calloway



# Flight Operations Summary

---

- Supported 619 SN events in August
  - 2 Yaw Maneuvers; now -X
  - 7 Delta-V Maneuvers
- 2 Anomaly & 6 Event Rpts, 3 Generic Late Acqs
  - AR #92: TRMM in Sun Acq mode
  - AR#93: N2 Pressurant level reduction
  - ER #240: WSC; Equip failure
  - ER #241 & 242: Late Acq; TDRS out of view
  - ER #243: No acq; Did not lock onto 01/04 Kbps event
  - ER#244 & 245 Late Acq; TDRS events out of view



# Flight Operations Summary

---

- Notable Events
  - Preparation/participation in Orbit Boost activities
  - Supported during & recovery; Sun Acq mode
  - Kalman Filter mode of operation
  - CMOC/JSC Lessons Learned activity
  - Attended meeting: NCC move to WSC
  
- FOT at full staff; no apparent problems



# Thermal / Electrical Subsystems

---

- The Thermal subsystem remains nominal
  - No operational issues during the 402.5 km boost or operationally after arrival
  
- The Electrical subsystem remains nominal
  - No operational issues during the 402.5 km boost or operationally after arrival



# RF Subsystem

---

- 3 Generic Late Acquisitions
  - 236/141100z 171 event: Locked up @ 141342z. One fwd reacq was sent. Dump/pb were performed. All data recovered.
  - 237/121400z TDE event: Locked up @ 121558z. One fwd reacq was sent. Dump/pb were performed. All data recovered.
  - 237/135100z TDE event: Locked up @ 135210z. One fwd reacq was sent. Dump/pb were performed. All data recovered.
- Frequency offsets (monthly average)
  - Transponder #1 = +736.543 Hz
  - Transponder #2 = -842.115 Hz
- 2 RF Event Reports and 1 MOCR this month
  - ER # 240: Dual Modulator Doppler Predictor fault was reported by CSC-3 for 217/1800z 171 event. All data was recovered.
  - ER # 243: Failure to acquire a TDE 1/4 K event at 226/0707z. CSC reported the event was scheduled as a 1/1 K event and not re-specified as a 1/4 K event. No data was lost.



# RF Subsystem

---

- FOT will create new configurations codes for coherent and non-coherent 1/4 K events for the NCC database.
- 2 Late Acquisitions and 2 Negative Acquisitions resulted from shifting view periods during the 402.5 km boost.
- Impact and lessons learned from Sun Acquisition:
  - 22 Negative Acquisitions and 1 Late Acquisition occurred from blocked view of the HGA over a period of 5 days.
  - Coherent low rate events will need to be scheduled sooner after transition to Sun Acquisition mode so that FDF can obtain more tracking data.
  - FOT and FDF will be working on ways to improve HGA view predictions.
  - FOT will avoid having both transmitters on at the same time.
- Upcoming Events
  - Offset of transponder 2 frequency may still occur this year.



# ACS Subsystem

---

- Transition to Sun Acq during Boost Activities on 01-225 (Mon., Aug 13<sup>th</sup>)
  - ESA Spikes during 3 & 4 Quadrant control resulted in accumulated yaw error and transition to Sun Acq. The Spikes were larger than 350km, because of lower signal to noise ratio at the higher altitude.
  - DSS-A marked bad, unable to perform Yaw update. Then ESA Quadrant 1 FDC reached 1<sup>st</sup> limit and placed ACE-B in control. ESA Quadrant 2 FDC 1<sup>st</sup> limit reached (no action taken since ACE-B was in control).
  - ESA Quadrant 1 FDC reached 2<sup>nd</sup> limit, and marked Quadrant 1 Bad. Then ESA Quadrant 2 FDC reached 2<sup>nd</sup> limit and marked Quadrant 2 Bad.
  - DSS-B marked bad, once both DSS's have been marked bad the ACS transitions to Sun Acq.
  - See Weekly Report (01 225-231) for more details.
- ACS placed in Contingency Mode on 01-228 (Thurs., Aug 18<sup>th</sup>)
  - Using Kalman filter for Attitude control.
  - No Re-Initializations of the Kalman filter were required following  $\Delta V$ s or Yaw Maneuvers.
  - Gyro reset commands now being placed before each  $\Delta V$  burn.





# FDS/C&DH Subsystems

---

- Boost/Sun Acq. Table Activities
  - ACS Tables #54 & #81: loaded to RAM, on 01-211 (Mon., July 30<sup>th</sup>)
  - S/C RTS #117, uplinked on 01-213 (Wed., Aug 1<sup>st</sup>)
  - ACS Tables #73 & #85: loaded to RAM, on 01-218 (Mon., Aug 6<sup>th</sup>)
  - ACS Tables #80, #81, #90, & #102: loaded to RAM, on 01-228 (Thurs., Aug 18<sup>th</sup>), for Kalman filter
  - ACS Table #51: loaded to RAM, on 01-229 (Fri., Aug 19<sup>th</sup>)
  - ACS Tables #59, #76, & #84: loaded to RAM on 01-235 (Thurs., Aug 23<sup>rd</sup>), 402.5 km operational tables.
  - ACS Tables #73 & #85: restored from EEPROM to RAM (Thurs., Aug 23<sup>rd</sup>)
  - ACS Table #64: DSS table performance being review for possible update, since the S/C is in contingency mode.



# FDS/C&DH Subsystems

---

- TO Status;
  - Since Contingency packets are constantly being dumped, there is a bandwidth problem on the low rate events.
  - Contingency mode packets are consuming all of remaining bandwidth which is preventing the event buffer from being dumped.
  - The rate at which the contingency mode packets are being dumped, will be changed to a lower rate to allow dumps to be performed.
- UTCF/FS Status;
  - Two Adjustments were performed. One on 01-218 (Mon., Aug 6<sup>th</sup>), and the other on 01-228 (Thurs., July 16<sup>th</sup>). The next on is expected on 01-268 (Tues., Sept 25<sup>th</sup>)
  - Current UTCF value is 31535996.818135 sec
  - A FS Adjustments was performed on 01-218 (Mon., Aug 6<sup>th</sup>), and the new value is x'7D2'. The next Adjustment is expected on 01-315 (Sun., Nov 11<sup>th</sup>), and will be adjusted to x'7DE'.



# FDS/C&DH Subsystems

---

- DS Quota Table Reallocation
  - Reallocated all but 2 blocks of the recorder space from CERES to Housekeeping, on 01-228 (Thurs, Aug 18<sup>th</sup>)
    - » Minimum of 2 blocks is required in each VR for Guardband
  - Housekeeping has over 7 hours of recorder time, instead of 4.
  - Since S/C was in Sun Acq, and all instruments were powered off, no science was lost during Quota reassignments.
- Planned RTS Changes
  - Nominal TDRS AOS RTS format changes to allow easier modification as DS storage status changes, and to simplify transponder offsets if required.
  - Initially will be performed with RTSs 65 - 68, other AOS RTSs may also be converted later.



# Power Subsystem

---

- Sun Acquisition Performance
  - C/D ratio was above 1.10 for the first 12 hours. The average C/D ratio for the Sun Acquisition period was 1.06.
  - Since sunlight is directly on the Solar Arrays at sunrise, the current peak prior to 12 A per Battery Constant Current Mode was 43 A. The current peak is approximately 23 A with the Solar Arrays at the 50 degree stops at sunrise. There was no noticeable change in the Battery Differential Voltage and therefore, no change in Battery 2 Cell 1.
- Open issues
  - Essential Bus Voltage Monitor Backup (S/C Processor Current)
  - Solar Array off-pointing for longer durations



# CERES/VIRS Instruments

---

- **CERES.**
  - Powered OFF.
- **VIRS**, continues to operate nominally.
  - Powered Off, from transition to Sun Acq. 01-225 (Mon., Aug 13<sup>th</sup>)
  - Powered On, on 01-229 (Fri., Aug 17<sup>th</sup>) at 21:28:51z, and placed into Outgassing mode.
  - Completed Outgassing Mode on 01-231 (Sat., Aug 19<sup>th</sup>) at 17:47:53z, and placed into normal science collection mode.
  - Two sets of VIRS Solar Calibrations were performed on 01-238 (Sat., Aug 26<sup>th</sup>).



# TMI / PR Instruments

---

- No Open Issues with the TMI instrument
  - TMI was powered off due to transition to Sun Acquisition mode. It was powered on again on August 17 (01-229) @ 20:22:43z after recovery from Sun Acquisition.
- No Open Issues with the PR instrument
  - New interference was reported with Madras, India and Huangmei, China
  - PR Range Bin offsets for bins 1-4, 46-49 were installed following the first Delta-V boost maneuver at a mean altitude of approximately 360 km
  - PR was powered off due to transition to Sun Acquisition mode on August 13th (01-225). PR was powered on again on August 17th (01-229) and was back in Observation mode @ 20:46:18; the Range Bin offsets were also re-installed @ 21:07:46.



# Ground System

---

- Emergency patch for MOPSS system scheduled for August 29; rollover problem would render MOPSS inoperable starting Sept 9th without the fix
- MP load Integrated Print problem due to memory leak still occurs intermittently - workaround is to perform soft reboot of the workstation and more frequent version file cleanup procedures
  - One possible long-term solution would be to switch from ISAM to Oracle
- /Hist1 4 GB External disk has failed again and will be replaced this week



# Upcoming Activities

---

- 0-2 Months
  - Perform any necessary FSW revisions due to new Kalman Filter mode of operations (ex: mag field epoch patches, DSS Parameters updates, etc.)
  - Perform any new sensor calibrations due to FDF analysis
  - Transfer most recent FSW changes to EEPROM once fully validated
  - Establish new trend baseline for full seasonal changes at the new operational altitude
  - Test and install new Transponder-2 AOS Offset Relative Time Sequences
  - Perform SA 55° offset long-duration test
  - Test and install new TDRS HGA AOS RTSs
  - Generate new ODB to include newly-defined derived mnemonics





# Upcoming Activities

---

- 2-3 Months
  - Complete testing and training with PSIB alternate telemetry patch
  - End Of Life Planning, Testing, and Simulations continue
  - Continue to close open CCRs, MOCRs, and MSR Action Items
  - Leonids 2001 will occur in November